
Attachment 4 - 574 Meander Valley Road Prospect Bushfire Hazard Report (Pages = 39)





Bushfire Hazard Assessment Report & Bushfire Hazard Management Plan

574 Meander Valley Road, Prospect





Prepared for (Client)

Grubb Consulting Group

C/- Ground Proof Mapping

PO Box 1027

LAUNCESTON TAS 7250

Assessed & Prepared by

Rebecca Green

Senior Planning Consultant & Accredited Bushfire Hazard Assessor

Rebecca Green & Associates


PO Box 2108 LAUNCESTON TAS 7250

Mobile: 0409 284 422

Version 1

3 December 2014

Job No: RGA-B110



Executive Summary

The proposed subdivision development at 574 Meander Valley Road, Prospect, is subject to the Bushfire Code and therefore must be assessed for bushfire threat.

Based on the generally low BAL classifications (between 12.5 - 19) the likelihood of the site being threatened by bushfire is low. Under extreme fire weather conditions future buildings at the site may be subject to fire however, bushfire protection mitigation measures have been taken to ensure the impact of any fire is low. The proposed location, topography, subdivision layout is good therefore minimising fire risk at the site.

The implementation of safe access and egress routes for each lot, establishment of water supply and construction of future buildings will be done in accordance with the requirements outlined in AS 3959-2009 Construction of Buildings in Bushfire Prone Areas. The provision of a Bushfire Management Plan for the site will ensure any fire risks to future development on the land will be minimal. On this basis, the proposal appropriately responds to the Bushfire Code.



Contents

Exe	cutive Summary	3				
Sche	edule 1 – Bushfire Report	5				
1.0	Introduction	5				
2.0	2.0 Site Description for Proposal (Bushfire Context)					
3.0	Bushfire Site Assessment	7				
	3.1 Vegetation Analysis	7				
	3.2 BAL Assessment – Subdivision	11				
	3.3 Specified Hazard Management Areas	15				
	3.4 Outbuildings	16				
	3.5 Road Access	16				
	3.6 Water Supply	17				
4.0	Bushfire-Prone Areas Code Assessment Criteria	17				
5.0	Layout Options	18				
6.0	Other Planning Provisions	18				
7.0	Conclusions and Recommendations	18				
Sche	edule 2 – Bushfire Hazard Management Plan	20				
Forr	m 55	22				
۸tta	schment 1 – Certificate of Compliance to the Bushfire-prone Area Code under Planning Directi	iνο				
No 5		25				
Atta	chment 2 – AS3959-2009 Construction Requirements	31				
Atta	chment 3 - Agri Park Industrial Subdivision - General Arrangement	32				
Refe	erences	33				



Schedule 1 - Bushfire Report

1.0 Introduction

The Bushfire Attack Level (BAL) Report and Bushfire Hazard Management Plan (BHMP) has been prepared for submission with a Planning Permit Application under the *Land Use Planning and Approvals Act 1993; Bushfire-Prone Areas Code* and/or a Building Permit Application under the *Building Act 2000 & Regulations 2004*.

The Bushfire Attack Level (BAL) is established taking into account the type and density of vegetation within 100 metres of the proposed building site and the slope of the land; using the simplified method in AS 3959-2009 Construction of Buildings in Bushfire Prone Areas; and includes:

- The type and density of vegetation on the site,
- Relationship of that vegetation to the slope and topography of the land,
- Orientation and predominant fire risk,
- Other features attributing to bushfire risk.

On completion of assessment, a Bushfire Attack Level (BAL) is established which has a direct reference to the construction methods and techniques to be undertaken on the buildings and for the preparation of a Bushfire Hazard Management Plan (BHMP).

1.1 Scope

This report was commissioned to identify the Bushfire Attack Level for the existing property. ALL comment, advice and fire suppression measures are in relation to compliance with *Bushfire-Prone Areas Code* of the Launceston Interim Planning Scheme 2012, the Building Code of Australia and Australian Standards, *AS 3959-2009, Construction of buildings in bushfire-prone areas*.

1.2 Limitations

The inspection has been undertaken and report provided on the understanding that:-


- 1. The report only deals with the potential bushfire risk, all other statutory assessments are outside the scope of this report.
- 2. The report only identifies the size, volume and status of vegetation at the time the site inspection was undertaken and cannot be relied upon for any future development.
- 3. Impacts of future development and vegetation growth have not been considered.

No action or reliance is to be placed on this report; other than for which it was commissioned.

1.3 Proposal

The proposal is for the development of a 4 Lot Subdivision + Balance at 574 Meander Valley Road, Prospect. One lot exists, the proposal is for an additional four lots.

Lot 1 will have an area of approximately 7.7 hectares and will front the new road.



Lot 2 will have an area of approximately 17.5 hectares and will also front the new road and new culde-sac.

Lot 3 will have an area of approximately 19.9 hectares and will also front the new road and new culde-sac.

Lot 4 will have an area of approximately 9.3 hectares and will also front the new cul-de-sac.

The balance lot will be approximately 141.6 hectares.

2.0 Site Description for Proposal (Bushfire Context)

2.1 Locality Plan




Figure 1: Location Plan of 574 Meander Valley Road

2.2 Site Details

Property Address 574 Meander Valley Road, Prospect	
Certificate of Title Volume 114487 Folio 1	
Owner	Beaumont Percival Grubb
Existing Use Rural	
Type of Proposed Work 4 Lot Subdivision + Balance	
Existing Structures Cottage and outbuildings	
Water Supply Reticulated supply	
Road Access New road and cul-de-sac	





3.0 Bushfire Site Assessment

3.1 Vegetation Analysis

3.1.1 TasVeg Classification

Reference to Tasmanian Vegetation Monitoring & Mapping Program (TASVEG) indicates the land in and around the property is generally comprising of varying vegetation types including:





3.1.2 Site & Vegetation Photos






View looking east of Lot 3

View looking southwest along powerline easement between Lots 3 and 4








View looking east of Lot 4








3.2 BAL Assessment – Subdivision

The Acceptable Solution in Clause 1.6.1 of E1.0 Bushfire-Prone Areas Code requires all lots within the proposed subdivision to demonstrate that each lot can achieve a Hazard Management Area between the bushfire vegetation and each building on the lot with distances equal to or greater than those specified in Table 2.4.4 of AS3959-2009 Construction of Buildings in Bushfire Prone Areas for **BAL** 19.


<u>Lot 1</u>

Vegetation classification AS3959	North □ North-East ⊠	South □ South-West ⊠	East ⊠ South-East □	West □ North-West ⊠
Group A		☐ Forest	☐ Forest	☐ Forest
Group B	☐ Woodland	☐ Woodland		☐ Woodland
Group C	☐ Shrub-land	☐ Shrub-land	☐ Shrub-land	☐ Shrub-land
Group D	☐ Scrub	☐ Scrub	☐ Scrub	☐ Scrub
Group E	☐ Mallee-Mulga	☐ Mallee-Mulga	☐ Mallee-Mulga	☐ Mallee-Mulga
Group F	☐ Rainforest	☐ Rainforest	☐ Rainforest	☐ Rainforest
Group G	☐ Grassland	☐ Grassland	☐ Grassland	☐ Grassland
	☐ Managed Land		☐ Managed Land	
Effective	☐ Up/0 ⁰	☐ Up/0 ⁰	☐ Up/0 ⁰	□ Up/0 ⁰
slope	⊠ >0-5 ⁰	□ >0-5 ⁰	⊠ >0-5 ⁰	□ >0-5 ⁰
(degrees)	□ >5-10 ⁰	□ >5-10 ⁰	□ >5-10 ⁰	□ >5-10 ⁰
	□ >10-15 ⁰	□ >10-15 ⁰	□ >10-15 ⁰	□ >10-15 ⁰
	□ >15-20 ⁰	□ >15-20 ⁰	□ >15-20 ⁰	□ >15-20 ⁰
Likely direction of bushfire attack	×		⊠	
Prevailing winds				
25014252	27 .20	21/2	4026	21/2
REQUIRED Distance to classified vegetation for BAL 19	27-<38m	N/A	18-<26m	N/A



<u>Lot 2</u>

Vegetation classification AS3959	North ⊠ North-East □	South ⊠ South-West □	East ⊠ South-East □	West ⊠ North-West □
Group A	☐ Forest	☐ Forest	☐ Forest	☐ Forest
Group B	☐ Woodland		☐ Woodland	
Group C	☐ Shrub-land	☐ Shrub-land	☐ Shrub-land	☐ Shrub-land
Group D	☐ Scrub	☐ Scrub	☐ Scrub	☐ Scrub
Group E	☐ Mallee-Mulga	☐ Mallee-Mulga	☐ Mallee-Mulga	☐ Mallee-Mulga
Group F	☐ Rainforest	☐ Rainforest	☐ Rainforest	☐ Rainforest
Group G	☐ Grassland	☐ Grassland	☐ Grassland	☐ Grassland
		☐ Managed Land		☐ Managed Land
Effective	☐ Up/0 ⁰	⊠ Up/0 ⁰	□ Up/0 ⁰	⊠ Up/0 ⁰
slope	□ >0-5 ⁰	□ >0-5 ⁰	□ >0-5 ⁰	□ >0-5 ⁰
(degrees)	□ >5-10 ⁰	□ >5-10 ⁰	□ >5-10 ⁰	□ >5-10 ⁰
	□ >10-15 ⁰	□ >10-15 ⁰	□ >10-15 ⁰	□ >10-15 ⁰
	□ >15-20 ⁰	□ >15-20 ⁰	□ >15-20 ⁰	□ >15-20 ⁰
Likely direction of bushfire attack		⊠		
Prevailing winds				
REQUIRED Distance to classified vegetation for	N/A	15-<22m	N/A	15-<22m
BAL 19				



<u>Lot 3</u>

Vegetation classification AS3959	North ⊠ North-East □	South ⊠ South-West □	East ⊠ South-East □	West ⊠ North-West □
Group A	☐ Forest	☐ Forest	☐ Forest	☐ Forest
Group B		☐ Woodland		☐ Woodland
Group C	☐ Shrub-land	☐ Shrub-land	☐ Shrub-land	☐ Shrub-land
Group D	☐ Scrub	☐ Scrub	☐ Scrub	☐ Scrub
Group E	☐ Mallee-Mulga	☐ Mallee-Mulga	☐ Mallee-Mulga	☐ Mallee-Mulga
Group F	☐ Rainforest	☐ Rainforest	☐ Rainforest	☐ Rainforest
Group G	☐ Grassland	☐ Grassland	☐ Grassland	☐ Grassland
	☐ Managed Land		☐ Managed Land	
Effective	☐ Up/0 ⁰	☐ Up/0 ⁰	□ Up/0 ⁰	☐ Up/0 ⁰
slope	□ >0-5 ⁰	□ >0-5 ⁰	⊠ >0-5 ⁰	□ >0-5 ⁰
(degrees)	⊠ >5-10 ⁰	□ >5-10 ⁰	□ >5-10 ⁰	□ >5-10 ⁰
	□ >10-15 ⁰	□ >10-15 ⁰	□ >10-15 ⁰	□ >10-15 ⁰
	□ >15-20 ⁰	□ >15-20 ⁰	□ >15-20 ⁰	□ >15-20 ⁰
Likely direction of bushfire attack	⊠		⊠	
Prevailing winds				
REQUIRED Distance to classified vegetation for BAL 19	23-<32m	N/A	18-<26m	N/A



<u>Lot 4</u>

Vegetation classification AS3959	North ⊠ North-East □	South ⊠ South-West □	East ⊠ South-East □	West ⊠ North-West □
Group A	☐ Forest	☐ Forest	☐ Forest	☐ Forest
Group B	☐ Woodland			
Group C	☐ Shrub-land	☐ Shrub-land	☐ Shrub-land	☐ Shrub-land
Group D	☐ Scrub	☐ Scrub	☐ Scrub	☐ Scrub
Group E	☐ Mallee-Mulga	☐ Mallee-Mulga	☐ Mallee-Mulga	☐ Mallee-Mulga
Group F	☐ Rainforest	☐ Rainforest	☐ Rainforest	☐ Rainforest
Group G	☐ Grassland	☐ Grassland	☐ Grassland	☐ Grassland
		☐ Managed Land	☐ Managed Land	☐ Managed Land
Effective	☐ Up/0 ⁰	☐ Up/0 ⁰	□ Up/0 ⁰	☐ Up/0 ⁰
slope	□ >0-5 ⁰	□ >0-5 ⁰	□ >0-5 ⁰	⊠ >0-5 ⁰
(degrees)	□ >5-10 ⁰	□ >5-10 ⁰	⊠ >5-10 ⁰	□ >5-10 ⁰
	□ >10-15 ⁰	⊠ >10-15 ⁰	□ >10-15 ⁰	□ >10-15 ⁰
	□ >15-20 ⁰	□ >15-20°	□ >15-20 ⁰	□ >15-20 ⁰
Likely direction of bushfire attack			⊠	
Prevailing winds				
REQUIRED Distance to classified vegetation for BAL 19	N/A	28-<40m	23-<32m	18-<26m



BAL – 19 The risk is considered to be MODERATE.			
	There is a risk of ember attack and burning debris ignited by windborne		
	embers and a likelihood of exposure to radiant heat. The construction		
	elements are expected to be exposed to a heat flux not greater than 19		
	kW/m ² .		

3.3 Specified Hazard Management Areas

Hazard management areas are to be established <u>and maintained</u> between the bushfire prone vegetation and the building at a distance equal to, or greater than the separation distance specified for the Bushfire Attack Levels (BAL) in table 2.4.4 of *Australian Standard 3959-2009 Construction of Buildings in Bushfire Prone Areas*.

Where the Hazard Management Areas can be increased around the building and the classified vegetation in accordance with table 2.4.4 of Australian Standard 3959, the risk from bushfire attack can reduce.

Distance from Predominant vegetation (with management plan)

Distance from Predominant vegetation for	North/ North-East	South/ South-West	East/ South-East	West/ North-West
Lot 1	38-<100	N/A	26-<100	N/A
BAL 12.5	metres	metres	metres	metres
Lot 1	27-<38	N/A	18-<26	N/A
BAL 19	metres	metres	metres	metres

Distance from Predominant vegetation for	North/ North-East	South/ South-West	East/ South-East	West/ North-West
Lot 2	N/A	22-<100	N/A	22-<100
BAL 12.5	metres	metres	metres	metres
Lot 2	N/A	15-<22	N/A	15-<22
BAL 19	metres	metres	metres	metres

Distance from Predominant vegetation for	North/ North-East	South/ South-West	East/ South-East	West/ North-West
Lot 3	32-<100	N/A	26-<100	N/A
BAL 12.5	metres	metres	metres	metres
Lot 3	23-<32	N/A	18-<26	N/A
BAL 19	metres	metres	metres	metres



Distance from Predominant vegetation for	North/ North-East	South/ South-West	East/ South-East	West/ North-West
Lot 4	N/A	40-<100	32-<100	26-<100
BAL 12.5	metres	metres	metres	metres
Lot 4	N/A	28-<40	23-<32	18-<26
BAL 19	metres	metres	metres	metres

The separation distance for the SPECIFIED Hazard Management Area is to be shown on the attached Bushfire Hazard Management Plan measured from the external walls (Façade) of the building in metres along the ground to the bushfire hazard vegetation (if applicable).

3.4 Outbuildings

Not applicable.

3.5 Road Access


Roads are to be constructed to provide vehicle access to the site to assist firefighting and emergency personnel to defend the building or evacuate occupants; and provide access at all times to the water supply for firefighting purposes on the building site.

Private access roads are to be constructed from the entrance to the property cross over with the public road through to the building and water storage area on the site. Private access roads are to be designed, constructed and maintained to a standard not less than a Modified 4C Access Road.

The newly formed roadway will be a Council maintained road upon completion of the subdivision.

Access over the balance lot in the case of an emergency is also a possibility via the power line easement.

Existing	Access via direct road frontage
Road Access and Driveways	
New	Private access driveway/ roads are to be
Road Access and Driveways	constructed from the entrance of the property
	cross over at the public road through to the
	dwelling and on-site dedicated firefighting water
	supply (where provided). Private access roads
	are to be designed, constructed and maintained
	to a standard not less than a "Modified 4C
	Access Road".



3.6 Water Supply

A building that is constructed in a designated bushfire prone area must provide access at all times to a sufficient supply of water for firefighting purposes on the building site.

The exterior elements of a Habitable building in a designated Bushfire prone area must be within reach of a 120m long hose (lay) connected to –

- (i) A fire hydrant with a minimum flow rate of 600L per minute and pressure of 200kpa; or
- (ii) A stored water supply in a water tank, swimming pool, dam or lake available for firefighting at all times which has the capacity of at least 10,000L for each separate building.

New	Fire hydrants are provided within the road
Reticulated Water Supply	reserve and within 120m hose lay of the
	habitable buildings. On site water supply is not
	required.

It should be recognised that although water supply as specified above may be in compliance with the requirements of the Building Code of Australia, the supply may not be adequate for all firefighting situations.

4.0 Bushfire-Prone Areas Code Assessment Criteria

Assessment has been completed below to demonstrate the BAL and BHMP have been developed in compliance with the Acceptable Solutions and/or the Performance Criteria as specified in the Bushfire-Prone Areas Code.

- **E1.4 Exemptions** Not applicable.
- **E1.5 Vulnerable Uses** Not applicable.

E1.6.1 Subdivision

E1.6.1.1	E1.6.1.1 Hazard Management Areas									
		Comments								
⊠ A1	(b)	Specified distances for Hazard Management Areas for BAL 19 as specified on the plan are in accordance with AS3959. The proposal complies.								
□ P1										
E1.6.1.2	Public Access									
		Comments								
⊠ A1	(b)	The proposed access for all lots is off a newly formed roadway, then over a private driveway approximately 4 metres wide. The newly formed roadway will be a Council maintained road upon completion of the subdivision. The private driveways will be constructed in accordance with A Modified 4C Access Road all-weather driveway which is compliant with the Code.								



		This will satisfy the requirement of TAS 3.7.4.1 Vehicular access and satisfy the acceptable solutions of E1.6.3.2.
□ P1		
⊠ A2		Not applicable.
□ P2	No PC	
E1.6.1.3	Water supply	y for fire fighting purposes
		Comments
⊠ A1	(b)	A ground ball fire hydrant is to be provided within 120m hose lay of a future building site on each lot within the new road reserve. The proposal complies.
		This will satisfy the requirements of TAS 3.7.4.2 Water Supply and the acceptable solutions of E1.6.1.3.
□ P1	No PC	
⊠ A2		Not applicable.
□ P2	No PC	

5.0 Layout Options

Not relevant to this proposal.

6.0 Other Planning Provisions

Not relevant to this proposal.

7.0 Conclusions and Recommendations

Mitigation from bushfire is dependent on the careful management of the site by maintaining reduced fuel loads within the hazard management areas and within the site generally and to provide sources of water supply dedicated for firefighting purposes and the construction and maintenance of a safe egress route.

The site has been assessed as requiring buildings to conform to or exceed BAL 19 requirements based on AS 3959 – 2009 Construction of Buildings in Bushfire Prone Areas.

Access

Access to individual lots will be constructed in accordance with AS3959-2009 Construction of Buildings In Bushfire Prone Areas.

Water Supplies

The property has access to a reticulated water supply and potential development areas are to be located within 120 metres of a fire hydrant.



Fuel Managed Areas


Hazard Management Areas as detailed within the plan shall be constructed and maintained as detailed in Schedule 2.


Balance Lot

The future stages of each lot and balance (if applicable) will have bushfire assessments undertaken at that point in time of planning application. The results of the assessment will be based on the planning scheme provisions at that point in time, the Bushfire Prone Areas Code at that point in time, the design and economy at that point in time.



Schedule 2 – Bushfire Hazard Management Plan





Form 55

CERTIFICATE OI	F SPECIALIST OR OTHER PERSON	(B	UILDI	NG WORK)	Reg	ulation 16	
To:	Grubb Consulting Group, C/- Ground	Owner /Agent	For	55			
	PO Box 1027	Address					
	Launceston	Suburb/postcode					
Certifier details:							
From:	Rebecca Green						
Address:	PO Box 2108			Phone No:		0409 284 422	
	Launceston	725	50	Fax No:			
Accreditation No:	BFP-116 Email address:	rgassociates.co	om.au	J			
(if applicable) Or qualifications and Insurance details:	Accredited to report on bushfire hazards under Part IVA of the <i>Fire Services Act 1979</i>	tion from Column 3 of irector of Building Con ination)		e 1			
Speciality area of expertise:	Analysis of hazards in bushfire prone areas	cion from Column 4 of 3 rector of Building Cont nation)		21			
Details of work:							
Address:	574 Meander Valley Road			L	ot No:	1	
	Prospect	725	50	Certificate of ti	tle No:	114487	
The work related to this certificate:	4 Lot Subdivision & Balance			(description of the work or part work being certified)			
Certificate detail	s:						
Certificate type:	Bushfire Hazard			tion from Column 1 of s rector of Building Cont nation)		2.1	
	This certificate is in relation t	to aı	n applic	ation for a new bu	ıilding	√ permit. <i>OR</i> √	
	This certificate is in relation to	any	stage c	of building work be	efore c	ompletion.	
In issuing this certifica	ate the following matters are relevant –						
Documents:	Bushfire Attack Level Assessment & Bushfire Hazard Management Plan	Rep	oort				
Relevant calculations:	N/A						

References:

Planning Directive No 5, Bushfire-Prone Areas Code Australian Standard 3959-2009

Guidelines for Development in Bushfire Prone Areas of Tasmania

Substance of Certificate: (what it is that is being certified)

- 1. Assessment of the site Bushfire Attack Level (BAL) to Australian Standard 3959
- 2. Bushfire Hazard Management Plan

Scope and/or Limitations

Scope

This report and certification was commissioned to identify the Bushfire Attack Level for the existing property. <u>All</u> comment, advice and fire suppression measures are in relation to compliance with *Planning Directive No 5, Bushfire-Prone Areas Code* issued by the Tasmanian Planning Commission, the *Building Act 2000 & Regulations 2004, Building Code of Australia* and *Australian Standard 3959-2009, Construction of buildings in bushfire-prone areas.*

Limitations

The assessment has been undertaken and report provided on the understanding that:-

- 1. The report only deals with the potential bushfire risk all other statutory assessments are outside the scope of this certificate.
- 2. The report only identifies the size, volume and status of vegetation at the time the inspection was undertaken and cannot be relied upon for any future development.
- 3. Impacts of future development and vegetation growth have not been considered.
- 4. No assurance is given or inferred for the health, safety or amenity of the general public, individuals or occupants in the event of a Bushfire.
- 5. No warranty is offered or inferred for any buildings constructed on the property in the event of a Bushfire.

No action or reliance is to be placed on this certificate or report; other than for which it was commissioned.

I certify the matters described in this certificate.

	Signed:	Date:	Certificate No.
Certifier:	1/2	3 December	RG-089/2014
	1/ Green	2014	



Attachment 1 – Certificate of Compliance to the Bushfire-prone Area Code under Planning Directive No 5

Code E1 – Bushfire-prone Areas Code

Certificate under s51(2)(d) Land Use Planning and Approvals Act 1993

Office Use

Date Received

Permit Application No

PID

1.	Land to which certificate applies ¹	
Name	of planning scheme or instrument: Launceston Interim Planning Sc	theme 2012.(The Scheme)
		1
Use or D	Development Site	Certificate of Title / PID
Street A	ddress	CT 114487/1 PID 1882447
	ander Valley Road t, Tasmania	
		0.115 1. (711 / 212
	at is not the Use or Development Site relied upon for bushfire hazard ment or protection	Certificate of Title / PID
Street A	ddress	
	Proposed Use or Development (provide a description in the space	
	below)	
4 Lo	ot Subdivision & Balance	
	Vulnerable Use	
	Hazardous Use	
\boxtimes	Subdivision	
	New Habitable Building on a lot on a plan of subdivision approved in according	ordance with Bushfire-prone Areas Code.
	New habitable on a lot on a pre-existing plan of subdivision	
	Extension to an existing habitable building	
	Habitable Building for a Vulnerable Use	

¹ If the certificate relates to bushfire management or protection measures that rely on land that is not in the same lot as the site for the use or development described, the details of all of the applicable land must be provided.

3. Documents relied upon²

	Document or certificate description:						
\boxtimes	Description of Use or Development ³ (Proposal or Land Use Permit Application)						
	Documents, Plans and/or Specifications						
	Title: Agri Park Industrial Subdivision – General Arrangement SK01-A						
	Author: IPD Consulting						
	Date: 02/10/14						
\boxtimes	Bushfire Report ⁴						
	Title: Bushfire Hazard Assessment Report & Bushfire Hazard Management Plan						
	Author: Rebecca Green						
	Date: 3 December 2014						
	5						
\boxtimes	Bushfire Hazard Management Plan⁵						
	Title: Bushfire Hazard Assessment Report & Bushfire Hazard Management Plan						
	Author: Rebecca Green						
	Date: 3 December 2014						
	Title: Bushfire Hazard Management Plan Map for Strathroy Agri Park Subdivision						
	Author: Justin Cashion, Ground Proof Mapping						
	Date: 27/11/2014						
	Other documents						
Ш							
	Title:						
	Author:						
	Date:						

² List each document that is provided or relied upon to describe the use or development, or to assess and manage risk from bushfire, including its title, author, date, and version.

³ Identify the use or development to which the certificate applies by reference to the documents, plans, and specifications to be provided with the permit application to describe the form and location of the proposed use or development. For habitable buildings, a reference to a nominated plan indicating location within the site and the form of development is required.

⁴ If there is more than one Bushfire Report, each document must be identified by reference to its title, author, date and version.

⁵ If there is more than one Bushfire Hazard Management Plan, each document must be identified by reference to its title, author, date and version

	4. Nature of Certificate ⁶						
	Applicable Standard	Assessment Criteria	Compliance Test: Certificate of Insufficient Increase in Risk		Compliance Test: Certified Bushfire Hazard Management Plan		Reference to applicable Bushfire Risk Assessment or Bushfire Hazard Management Plan ⁷
	E1.4 – Use or development exempt from this c						
	E1.4. (identify which exemption applies)		No specific measures required because the use or development is consistent with the objective for each of the applicable standards identified in this Certificate		Not Applicable		
	E1.5.1 - Vulnerable Use						
	E1.5.1.1 – location on bushfire-prone land	A2	Not Applicable		Tolerable level of risk and provision for evacuation		
	E1.5.2 - Hazardous Use						
	E1.5.2.1 – location on bushfire-prone land	A2	Not Applicable		Tolerable level of risk from exposure to dangerous substances, ignition potential, and contribution to intensify fire		
\boxtimes	E1.6.1 - Subdivision						
	E1.6.1.1 - Hazard Management Area	A1	No specific measure for hazard management		Provision for hazard management areas in accordance with BAL 19 Table 2.4.4 AS3959		
	E1.6.1.2 - Public Access	A1	No specific public access measure for fire fighting		Layout of roads and access is consistent with objective	\boxtimes	
	E1.6.1.3 - Water Supply	A1	No specific water supply		Not Applicable		
				•			

⁶ The certificate must indicate by placing a X in the corresponding \Box for each applicable standard and the corresponding compliance test within each standard that is relied upon to demonstrate compliance to Code E1

 $^{^{7}}$ Identify the Bushfire Risk Assessment report or Bushfire Hazard Management Plan that is relied upon to satisfy the compliance test


		Reticulated water	for fire fighting				
		supply					
		A2	No specific water supply		Water supply is consistent with	\boxtimes	
		Non-	measure for fire fighting		objective		
		reticulated					
		water					
		supply					
	E1.6.2 - Habitable Building on lot on a plan of	subdivision app	 proved in accordance with Co	de			
	E1.6.2.1 - Hazard Management Area	A1	No specific measure for		Provision for hazard management		
			hazard management		areas in accordance with BAL 19		
					Table 2.4.4 AS3959 and managed		
					consistent with objective		
	E1.6.2.2 – Private Access	A1	No specific private access		Private access is consistent with		
			for fire fighting		objective		
		A2	Not Applicable		Private access to static water		
					supply is consistent with objective		
	E1.6.2.3 - Water Supply	A1	No specific water supply		Water supply is consistent with		
			measure for fire fighting	ļ.,	objective		
Ш	E1.6.3 - Habitable Building (pre-existing lot)						
	E1.6.3.1 - Hazard Management Area	A1	No specific measure for		Provision for hazard management is		
			hazard management		consistent with objective; or		
					Provision for hazard management		
					areas in accordance with BAL 29		
					Table 2.4.4 AS3959 and managed		
					consistent with objective		
	E1.6.3.2 - Private Access	A1	No specific private access		Private access is consistent with		
			measure for fire fighting		objective		
		A2	Not applicable		Private access to static water		
					supply is consistent with objective		
	E1.6.3.3 - Water Supply	A1	No specific water supply		Water supply is consistent with		
			measure for fire fighting		objective		

E1.6.4 - Extension to Habitable Building				
E1.6.4.1 – hazard management	A1	No specific hazard management measure	Provision for hazard management is consistent with objective; or	
			Provision for hazard management areas in accordance with BAL 29 Table 2.4.4 AS3959 and managed consistent with objective	
E1.6.5 – Habitable Building for Vulnerable Use				
E1.6.5.1 – hazard management	A1	No specific measure for hazard management	Bushfire hazard management consistent with objective; or Provision for hazard management areas in accordance with BAL 12.5 Table 2.4.4 AS3959 and managed consistent with objective	

5.	Bushfire H	lazard Practitioner – Accredited Per	son			
Name	Rebecca	Green		Phon	(1/4)	9 284 422
Address:	PO Box 2 Launcest	Fax No):			
			Email address:	admin@	rgasso	ciates.com.au
Fire Service Accreditat	<i>e Act 1979</i> ion No:	BFP-116	Scope:	1, 2, 3A,	3B	
6.	Certification	on				
The Bus incr	hfire-Prone n rease in risk t hfire protect	,	npt from applic cause there is a	cation of Coo an insufficier ment and/or	le E1 – nt	the Part 4A of
or The	ere is an insu	fficient increase in risk to warrant specific n	neasures for b	ushfire hazai	rd	
ma. con	nagement ai	nd/or bushfire protection in order for the us the objective for each of the applicable sta	se or developm	nent describe	d to be	
and/or						
acc dev	ordance witl elopment de	zard Management Plan/s identified in Sect th the Chief Officer's requirements and can a escribed that is consistent with the objective applicable standards identified in Section 4	leliver an outc	ome for the l	ise or	

Signed

Date: 3 December 2014



Attachment 2 – AS3959-2009 Construction Requirements

VERANDAS DECKS ETC.	ROOFS	EXTERNAL DOORS	EXTERNAL WINDOWS	EXTERNAL WALLS	FLOORS	SUBFLOOR SUPPORTS	
No special construction regularments	No special construction requirements	No special construction requirements	No special construction requirements	No special construction requirements	No special construction requirements	No special construction requirements	BAL-LOW
As for BAL-19	As for BAL-19	As for BAL-19 except that door framing can be naturally fire resistant (high density) further	As for BAL-19 except that 4 mm Grade A safety glass can be used in place of 5 mm toughened glass	As for BAL-19	No special construction reguliernents	No special construction requirements	BAL-12.5
Exclused sub-floor space—no special registement for materials energy within 600 mm of ground. No special registements for supports of arange. Desting to be now constitute or busher restant within 300 mm horizontally and 400 mm vertically from a gland delement.	Non-combat the covering Rodfwall partition sealed. Opening: titted with non-combattale entire guards food to be fully safeed.	Protected by healthreshelts or screened with task, broate or all amends or glazed with 5 mm trappened glass, non-combistible or 35 mm oxid timber for 400 mm above threshol, media or bushle restring timber framed to 400 mm above growt, decking, etc. tight fitting with weather strips at base decking, etc. tight fitting with weather strips at base.	Protected by bushler shatter, completely screened with steel, bronze or aluminam mesh or 5 mm traphened gases or glass blocks within 400 mm of ground, deck etc. Openable portion mest screened with time of metal or media environed PVC-U or bushler resisting timber	External walls - Parts less than 400 mm above ground or declar et: to be of non-combactible material, 6 mm then commercial or bushfer resistant/naturally fire resistant/then	No special construction requirements	No special construction requirements	BAL-19
Enclo bushfi	Non-	with comb above fram	Protect with toughe frame o resisting	Non-c mux fram and d	Con wall, n natur natur under	Ends alumin the su	
Enclosed sub-floor space or non-combustable or bushine resistant timber supports. Declarg to be non-combustable	Non-combustible covering, Boofwall junction sealed. Openings fitted with non-combustible ember guards. Boof to be fully safeed	Protected by busiline shutter, or screened with steet, bronze or aluminium mech or non- combustible, or 35 mm sold timbels for 400 mm above threshold. Metal or busiline resisting timber framed tight fitting with weather strips at base framed tight fitting with weather strips at base	Protected by bushine shutter or completely screened with Steel, Yomes or aluminium mesh, or 5 mm toughened signal operable portion, or exact and fame of mesk of separable portions VPC-UL, or exact and fame or mesk in operable portion within 400 mm of ground level screened.	Non-combustible malerial (masorry, brita veneer, mulbrixt, aerated concrete, concrete), turber framed, steel framed walls sarked on the outside and dad with 6 mm fibre cement sheeling or steel sheeting or bushine resistant tumber	Concrete slab on ground, enclosure by external wall, metal mesh as above or flooring less than 400 mm above ground level to be non-combustible, and urally the resistant timber or protected on the underside with safting or miterial wood insulation.	Enclosure by external wall or by steet, bronze or starmham mest, non-consustitée supports where the subfloor is unexclosed, naturally the resistant timber stumps or posts on 75 mm mestal stumps	BAL-29
Enclosed sub-floor space or non-combustible supports. Decking to be non-combustible	Non-contestible covering Boodwall junction scaled. Opening fitted with non-contectible ember guerts. Boof to be lifty satisfact and no roof mounted evaporative coolers.	Protected by bushine shufter, non-combustible or 35 mm sold timber, metal framed tight litting with weather strips at base	Protected by beather statter or 5 mm toughward glass. Openable portion screened with steel or broate mech	Non-combustible material (masoury, birck veneer, mud birch, seatled concelle, concrete) of timber famed or steel famed rails safe on the outside and clad with 9 mm filter coment sheeting or steel sheeting or be steed for brushible mesticance to AS 1530.8.1	General state on ground, enclosure by external wall or protection of underside with a non-combostible material such as fine connect sheet or be non-combostible or be tested for suchine resistance to AS 150.8.1	If exclosered by external well refer below "External Walls" section in table or non-combostities solution supports or tested for modifier resistance to AS 1530.81	BAL-40
Enclosed sub-floor space or non-combustible supports. Declaring to have no gaps and be non-combustible	Roof with FRI. of 30/30/30 or tested for bushler restance to AS 1530 8.2. Roof/wall junction scaled. Openings fitted with non-combustible ember guards. No roof mounted evaporable coolers	Protected by bushine shutter or tight fitting with weather stips at base and an FRL of -/3'U-	Protected by bushine shutter or FIL of -/30/- and operable portion screened with steel or borner much or be tested for bushine resistance to AS 1530.8.2	Non-combustible material (masony, brist vener, mud brist, aerated concrete, concrete) with minimum thickness of 90 mm or an Fit of 470 90 when tested from outside or the tested for bushfle resistance to AS 1530.8.2	Concrete slab on ground or enclosure by external wall or an FRL of 30/30/30 or protection of underside with 30 minute incipient spread of the system or be tested for bashine resistance to AS TSO 8.2	Subfloor supports - enclosure by enternal will or non-combustible with an Fil. of 304- or the tested for bushine resistance to AS 15308.2	BAL-FZ (FLAMEZONE)



Attachment 3 – Agri Park Industrial Subdivision - General Arrangement





References

- (a) Tasmanian Planning Commission 2012, *Tasmanian Planning Directive No. 5, Bushfire-Prone Areas Code*, Tasmania.
- (b) Tasmania Fire Service 2005, *Guidelines for Development in Bushfire Prone Areas of Tasmania*, Tasmania.
- (c) Australian Standards, AS 3959-2009, *Construction of buildings in bushfire-prone areas*, Standards Australia, Sydney NSW.
- (d) Resource Management & Conservation Division of the Department Primary Industry & Water September 2006, TASVEG, *Tasmanian Vegetation Map*, Tasmania.
- (e) Tasmanian Government, Land Information System Tasmania, www.thelist.tas.gov.au






Addendum

Bushfire Hazard Assessment Report & Bushfire Hazard Management Plan

574 Meander Valley Road, Prospect



Prepared for (Client)

Grubb Consulting Group

C/- Ground Proof Mapping

PO Box 1027

LAUNCESTON TAS 7250

Assessed & Prepared by

Rebecca Green

Senior Planning Consultant & Accredited Bushfire Hazard Assessor


Rebecca Green & Associates

PO Box 2108 LAUNCESTON TAS 7250

Mobile: 0409 284 422

6 May 2015

Job No: RGA-B110



Addendum

Further to the Bushfire Hazard Assessment Report and Bushfire Hazard Management Plan prepared 3 December 2014 for a four lot subdivision at 574 Meander Valley Road, Prospect; this addendum has been prepared to provide additional information to the Launceston City Council for an indicative future layout of 66 lots.

Although the proposal does not entirely assess the 66 indicative lots, the Bushfire Hazard Management Plan has been overlayed (dated 6/5/2015 – see attached) to demonstrate that each future lot could contain a building envelope into the future of BAL-19. In fact, approximately 50% of the indicative lots could have their total site within the BAL-Low rating.

It is noted that even though each future indicative lot contains a significant large area within BAL-Low, or BAL-12.5 or BAL-19, there are a number of the lots, around the perimeter that have a "building exclusion zone". Within this area though can contain non-habitable buildings and structures provided that there is a minimum separation with a habitable building or structure of at least 6 metres; other useable areas associated with future permissible uses that are not buildings or structures such as car parking; or open storage areas, for example.

Other options to reduce or mitigate the "building exclusion zone" at a later stage of subdivision (further than the 4 lots provided as part of this submission) and/or building stage upon each lot could see alternatives, such as a conversion of the vegetation group, such as forest to woodland by reduction of the fuel load, although threatened species will need further investigation for this option. Alternatively a grassland fire buffer could be implemented outside the boundaries of the subdivision.

It is deemed unnecessary to undertake any of the aforementioned mitigation measures at this stage, as the proposal clearly demonstrates that each lot is suitable for future permissible uses by way of rezoning the subject site. It is demonstrated that future indicative lots can be built on with habitable buildings to a low to medium risk level in terms of bushfire protection.

Rebecca Green

1/ Green

Accredited Bushfire Hazard Assessor BFP - 116

